

## **Facilities Management**

POLICY: CHECKING IN-GROUND HYDRAULIC CYLINDERS FOR ELEVATORS	NUMBER: S-22
	Page 2 of 2

4.18.3.8 of B44 Code, Supplement 1-1992.

If leaking is suspected on in-ground cylinders that have a protective plastic casing, the space between the casing and the cylinder must be blown out using compressed air.

The contents will be collected to determine any leakage from the cylinder.

- 4. Shut off the line valve.
- 5. Leave the car off for 15 minutes and determine how much the car sinks.

If there is further doubt as to the soundness of the cylinder, a \*static test must be carried out.