



ASBESTOS CONTROL POLICY

PREPARED BY: OCCUPATIONAL HEALTH & SAFETY
APPROVED BY: OCCUPATIONAL HEALTH & SAFETY

EFFECTIVE DATE: August 3, 2006

REVISION: January 21, 1997 (updated January 2013)

INTRODUCTION

Many construction and insulation materials contain asbestos. These materials, if removed, or disturbed in an uncontrolled manner, can release asbestos fibres into the air, possibly causing a health hazard. The disturbance and mishandling of the Asbestos-Containing Materials (ACM) can result from activities performed in close proximity to, and not necessarily on asbestos-containing insulation materials. All personnel working with, or in proximity to where there is a likelihood of disturbance to the friable asbestos products must be informed by their

RESPONSIBILITY

Compliance with this policy is the responsibility of the supervisors of personnel at all levels within administrative, faculty, and ancillary operations, or supervisors of contracted activities where workers may come in contact with ACM.

All uncontrolled asbestos-disturbance incidents must be reported immediately upon discovery. An incident report is also required from each affected person's supervisor. It is understood that

Facilities Management and Maintenance

REQUIREMENTS

- (a) All handling, renovations, maintenance activities, construction, demolition, and other projects in areas containing ACM, must be performed in accordance with relevant Facilities Management Work Procedures. In situations where these written procedures do not address specific circumstances, appropriate measures must be taken to control the release of asbestos fibres to protect all building occupants. Both Facilities Management and OHS are to be consulted when such matters arise.

- (b) University staff and contractors shall not attempt to handle or work in close proximity to ACM without first obtaining the Asbestos Awareness training, in accordance with the OccupOccupi2 (H)-6e)4 (a)4 (l)3 (t)-2 (h)2 (a)4 (n)-6d)2 S(a)4 (f)1ety ct84 (,)-4 RieulOccn , ectccu training, indiviual-12.2 (s)-13 (w)14 idll not be permitted tooror in clo46(se)2 (p)4 (ro)-6vimit72 (y)